INSPECTION Page 1 of 3



OTHER TROMMEL SCREEN

INSPECTION DETAILS

| Inspection Type | CUSTOMER |
|-------------------|-------------------|
| Inspection # | 2566014 |
| Inspection Status | INSPECTED |
| Created | 12/18/18 13:36:31 |
| Updated | 12/20/18 07:26:33 |
| Created By | Page, Austin |
| Inspector | Wells, Marshall |

| Wells, Marshall |
|-------------------------------|
| Page, Austin |
| 7207102 |
| 390 |
| 4462245 CAT C4.4 |
| Greenville, SC, United States |
| |

FEATURES

CE PLATE

ULTRA LOW SULFUR DIESEL FUEL

NOTES

THIS IS A ROCKSTER MACHINE.

INSPECTION Page 2 of 3

Good Fair Poor

Approved Repair

GENERAL APPEARANCE

Crankcase Guard / Battery Box battery hold down intact Eng. Enclose Hood / Stack sheet metal in good condition-access doors hinge latch & prop well Fuel Tank metal tank--cap intact--no leaks--dual sight glass

Main Frame Welds no issues found ••• Paint paint in good condition

••• Radiator Grill & Shroud grill is straight

Notes - GENERAL APPEARANCE

machine has a small dent in Is at rearcosmetic only, no structural damagemachine is 1 yr old w/ low hrs & is overall reflective of light use

SAFETY ITEMS

Notes - SAFETY ITEMS all emergency shut down switches work well--travel alarm functions well & correct decibel

GAUGES, OPERATOR STATION, CONSOLE

Switches all working--machine has wireless remote & corded remote for operation--customer has all remotes

ENGINE

Air Cleaner dirty

••• Fuel Injection System no leaks found

NO Blow By

NO Water in Oil

Engine Supports

••• Radiator clean--good air flow--grill in good condition

NO Knocking

Fluid Levels all fluid levels correct

Turbocharger / Blower all heat shields & wrap intact-no leaks found

NO Oil Leaks

